



Installation instructions for CIRKO, FRICK, FRACK, RING, SLOT, DEMI SLOT, SQUIGGLE, QUY & WINK LED SURFACE MOUNT

FAILURE TO FOLLOW THESE INSTRUCTIONS WILL VOID WARRANTY

RISK OF ELECTRICAL SHOCK. THIS EQUIPMENT IS TO BE INSTALLED BY A QUALIFIED ELECTRICIAN ONLY. MAKE CERTAIN ELECTRICAL SUPPLY CIRCUIT IS DE-ENERGIZED BEFORE BEGINNING INSTALLATION. CHECK FIXTURE LABEL FOR CORRECT VOLTAGE. READ ALL INSTRUCTIONS CAREFULLY.

INSTALLATION

1. The lighting fixture comes fully assembled.
2. Remove lens assembly. Remove tray assembly by loosening the two 6-32 cap head screws. **Be careful not to touch the static sensitive LED board.** Connect the body to a standard outlet. Designplan recommends that the contractor utilize the four mounting holes in the back of the body to mount to the structure as well. It is the contractor's responsibility to supply proper anchorage based on job conditions. It is also the contractor's responsibility to caulk the back of the fixture in order to satisfy wet label requirements.
3. Unplug the amp connector. Make supply lead connections in the body using the female amp connector. Fixture is set up for three different light levels. The black wire marked "low output" has 9 LED's connected to it and the wire marked "medium output" has 16 LED's connected to it. In order to get the max output of 25 power both power to both feeds. **CONNECT GREEN WIRE TO "GROUND", CONNECT BLACK FIXTURE WIRE AS NOTED ABOVE TO BLACK BUILDING WIRE AND CONNECT WHITE FIXTURE WIRE TO WHITE BUILDING WIRE.** Plug amp connector back together.
4. Secure the tray inside the body.
5. Affix the grill and lens over the housing.

